

# **EXHIBIT F-3**

# Attachment 3

OIS-OMT: [REDACTED]

## Outage Dispatch Tool (Read Only)

Version 1.6 (3/30/2013)

<b>OIS #:</b> 1404752 Paradise (17)	<b>1st Call:</b> 14:48 07/14/2021	<b>Comments for Customers:</b> [REDACTED]
<b>Substation:</b> 10283 (PARADISE)	<b>Addr.:</b> 13586 BADER MINE RD, PARADISE	Our preliminary determination is that your outage was caused by an equipment issue in your area. PG&#38;E Personnel are investigating the cause.
<b>Circuit:</b> 102831105	<b>SSD:</b> [REDACTED]	
<b>Outage Dev.:</b> {1291}	<b>Outage Remarks:</b> OR:N/A-15 MIN ETA [REDACTED] 15:20 07/14/2021	<div style="display: flex; justify-content: space-between;"> <span>Find / Reset</span> <span>Verify</span> </div> <div style="display: flex; justify-content: space-between;"> <span>Clear</span> <span>Restore</span> </div> <div style="display: flex; justify-content: space-between;"> <span>Print</span> <span>Trouble Reports</span> </div> <div style="display: flex; justify-content: space-between;"> <span>Save</span> <span>Affected Customers</span> </div> <div style="display: flex; justify-content: space-between;"> <span>Exit</span> <span>Upgrade to xfmr</span> </div>
<b>Dev. Addr.:</b> 630° NE/O BADER MINE RD; 340° NW	<b>Repair Time:</b> 04:00 Duration (HH MM)	
<b>Level:</b> DEVICE	<b>ETOR:</b> 23:59 07/14/2021 <span style="color: red;">3 updates</span>	
<b>Hazard:</b> Wire Down Outage	<b>IVR Cause:</b> REPAIR WIRE DWN	
<b>Customers:</b> 0	<b>Access:</b> Available	
<b>Start Time:</b> 14:48 07/14/2021	<b>Assigned DO:</b> [REDACTED] <b>Contact:</b> [REDACTED]	
<b>Complete:</b> 22:50 07/14/2021		

### Crew Information

**Repair Crew Requested:** 17 00 07/14/2021

Seq.#	Name	Type	Crew Size	Dispatch	Enroute	ETA	Onsite	Stop
1	[REDACTED]	REPAIR	3	17:10 07/14/2021	18:25 07/14/2021	20:00 07/14/2021	19:05 07/14/2021	22 56 07/14/2021
2P	[REDACTED]	T-MAN	0	15:17 07/14/2021				15:18 07/14/2021
3S	[REDACTED]	T-MAN	0	14:51 07/14/2021	14:53 07/14/2021		15:22 07/14/2021	17:10 07/14/2021

### FAS Crew Comments

**FAS Crew Comments (Outbound):**

~LAT:LONG 39.79973:-121.58492 , FUSE 1291-120H TYPE ELF~

**FAS Crew Comments (Inbound):**

[REDACTED] (14-JUL-21 17:10)  
WIRE DOWN, OAK TREE, CREW TO RPR WIRE DOWN

### Material Information

<b>Poles:</b> 0	<b>Pri Spans:</b> 75	<b>Quantity &amp; Description (Pole type, X-ARM, Insulation, etc.):</b> SAP 100400403 2 ACSR, SLEEVES 75 CONDUCTOR OH:2 ACSR:BROKEN/DAMAGED / REPLACE / PART SET 4 CONN/SPLICE OH:SLEEVE COMPRESSION ACSR:BURNT / REPLACE
<b>Transformer:</b> 0	<b>Sec Spans:</b> 0	
<b>Service:</b> 0	<b>X-Arm:</b> 0	
<b>Joint Pole:</b> <input type="checkbox"/>	<b>Tree Crew:</b> <input type="checkbox"/>	<b>Personnel &amp; Equipment (Flagman, CHP, Public works, Spill Kit, Boom Trk, etc.):</b> SAP 100400403 Personnel Remarks: CREW 3 Setup Remarks: SMALL BUCKET OK, DIRT DRIVEWAY