

**The Following information regarding this incident has been reported:**

**Reporting Date:** 8/2/2021 8:06:47 PM

**Incident Date:** 7/22/2021 @ 00:00 a.m.

**Reported By:** [Redacted]

**Utility Name:** PG&E

**Phone Number:** [Redacted]

**Email Address:** [Redacted]

**Incident Location:** Butterfly Valley Twain Road and Highway 70 Quincy, Las Plumas

**Reasons For Reporting:**

- Fatalities? No (Utility: , Others: )
- Names of Fatalities:
- Injuries? (Utility: , Others: )
- Names of Injured:
- Damage? No (Utility: , Others: )
- Interruption? (Total Customers: , Total Hours: )
- Operator Judgement? No
- Media Coverage? Yes

**Cause of Incident:** No Cause Selected (Other Cause: )

**Agencies on Scene:**

**Facilities Affected:**

- Utilities Facilities: Gansner 1101
- Voltage (KV): 12 kV
- Customer's Facilities:

**DigIn Information:**

- Excavator Name:
- Contact:
- Phone: (\_\_\_\_)\_\_\_\_-\_\_\_\_

**Incident Recovery:**

- On Scene Date & Time: @ 00:00 a.m.
- Service Restored: @ 00:00 a.m.

**Summary:** On July 22, 2021, a wildfire began in the area of Butterfly Valley Twain Road and Highway 70 in Plumas County, California (the Fly Fire). The National Wildfire Coordinating Group website (the website) reported as of July 25, 2021 at 0000 hours that the Fly Fire had consumed 4,300 acres and was 5% contained and that, as of the night of July 24/25, the Fly Fire had merged with the Dixie Fire and that the website would not be providing further updates on the Fly Fire. At approximately 1701 hours on July 22, 2021, wildfire cameras first showed smoke in the general direction of Butterfly Valley Twain Road and Highway 70. According to PG&E's records, SmartMeters and a line recloser on the portion of the PG&E distribution line serving the area, the Gansner 1101 circuit, reported alarms and other activity

between approximately 1650 and 1810 hours, when that portion of the line was deenergized. On August 2, 2021, PG&E assisted the U.S. Forest Service (USFS) with moving and examining a tree that was resting on conductor on the Gansner 1101 circuit. PG&E is cooperating with the USFS's investigation and is reporting this to the CPUC under the media criterion. The data currently available to PG&E do not establish the cause of the Fly Fire. This information is preliminary.