

EXHIBIT F-2

Attachment 2

Det
Chico 7/13/2021

Tech Info			Dispatch Info					FO Timestamp Info				Elapsed Times						Order Info												
Area	HQ	Tech	Order State	Order Dispatch Count	Dispatch User ID	Last Dispatch Timestamp	Returned to Pending	Date Taken Timestamp	Enroute Time	Onsite Time	Completed Time	Total Time Billed To Order	En Route Minutes	Expected HQ Drive Time	Variance	On Site Minutes	Total Expected CC Time	Variance	Order Number	Priority	Appointment Window	Address	Job Code 1	CC1	CC2	CC3	CC4	Office Remarks	Dispatcher Remarks	Tech Remarks
	Chico		Completed	6		07/13 07 02		07/01 12 48	08 21	08 43	09 12	50.8	21.8	10	11.8	29.0	29.0	0.0	0723599973	2	AD							EMT.. INSTALL 200A 120/240 MTR CTC REP NOT #1196600225		Insta l serv, set mtr, chk volt ok. Left main off
			Completed	6		07/13 07 02		07/01 13 04	09 12	09 12	09 28	15.6	0.0	10	-10.0	15.5	29.0	-13.5	0727711720	2	AD							EMT.. INSTALL 200A 120/240 MTR CTC REP NOT #1196600225		Insta l ser, chk volt and set mtr. Left main off
			Completed	6		07/13 07 02		07/01 12 35	09 28	09 28	09 46	18.4	0.0	10	-10.0	18.4	29.0	-10.6	0729799710	2	AD							EMT.. INSTALL 200A 120/240 MTR CTC REP NOT #196600225		Insta l ser, chk volt ok, set mtr. Left main off
			Completed	6		07/13 07 02		07/01 13 02	09 47	09 47	10 01	14.2	0.0	10	-10.0	14.2	29.0	-14.8	0720969708	2	AD							EMT.. INSTALL 200A 120/240 MTR CTC REP NOT #196600225		Insta l serv, chk volt and set mtr. Left main off
			Completed	2		07/13 10 28		07/13 10 26	10 53	11 21	11 43	49.9	27.6	10	17.6	22.3	20.0	2.3	6713119073	1	AD							GIVE TO TMEN		Insp panel repairs ok, reconn and chk volt ok. Mtr tech to change out bad mtr
			Completed	4		07/13 10 47		07/13 09 36	11 43	12 29	23 02	678.6	45.7	10	35.7	632.9	25.2	607.7	0009119619	1	AD	UNKNOWN PREMISES DO NOT CHANGE STORRIE						CHECK FUSE 806 -BUCKS CREEK 1101 - PER D O	PARADISE TAG PER TMEN	Found tree on line with 2 fuses down and 1 still energized, open remaining. Ca led for 911
			Reassigned	1		07/13 13 04		07/13 13 04			14 59								T005340710	0	AD						AXIS-LOCKED GATE 3 DOGS LAB MIXER- WAS WORKING IN THE CUSTOMERS YARD AND HIT AN ELEC TRIC LINE THEY WERE ABLE RESET THE BREAKER FOR POWER			
	Chico		Completed	5		07/13 06 54		07/08 14 56	07 07	10 13	10 15	187.7	185.9	10	175.9	1.9	20.0	-18.1	0667878152	2	AD						(2) T-MAN TO INSTALL 140' NEW 4/0 TPX SVC & SET 200A 120/240 1P B10S MTR - FLD CNT REP TAG ON 2 TMEN		set meter	
			Completed	1		07/06 19 04		07/06 19 04	10 19	10 55	11 32	72.8	35.7	10	25.7	37.1	0.0	37.1	W106700003	2	UD									

Det
Chic

7/13/2021

Tech Info			Dispatch Info					FO Timestamp Info				Elapsed Times						Order Info													
Area	HQ	Tech	Order State	Order Dispatch Count	Dispatch User ID	Last Dispatch Timestamp	Returned to Pending	Date Taken Timestamp	Enroute Time	Onsite Time	Completed Time	Total Time Billed To Order	En Route Minutes	Expected HQ Drive Time	Variance	On Site Minutes	Total Expected CC Time	Variance	Order Number	Priority	Appointment Window	Address	Job Code 1	CC1	CC2	CC3	CC4	Office Remarks	Dispatcher Remarks	Tech Remarks	
			Completed	1		07/13 07 48		07/13 07 48	11 58	11 58	13 43	105.6	0.0	10	-10.0	105.5	5.6	99.9	T005340260	0	AD		9190	0930					AXS-OK NON CUSTOMER STATES BRANCHES ENTANGLED IN LINES CAUSING WIRE TO SAG . MOVE IN ANOTHER DIRECTION, FEELS HAZARDOUS, NEAR CH ICO HIGH SCHOOL		Phone
			Completed	1		07/13 14 59		07/13 14 59	14 59	15 52	15 53	53.6	52.8	10	42.8	0.8	5.6	-4.8	T005340856	0	AD		9060	0930				AXS-LOCKED GATE SYSTEM. 3 DOGS LAB MIXES- WAS WORKING IN THE CUSTOMERS YARD AND HIT AN ELEC TRIC LINE THEY WERE ABLE RESET THE BREAKER FOR POWER		customer side of meter	
			Completed	4		07/13 14 58		07/13 12 27	15 57	16 40	16 41	43.6	42.8	10	32.8	0.8	5.6	-4.8	0689701891	0	AD		1160	0930				No Access or Safety Issues; POLE TO CALLERS HOUSE; WIRE HANGING 2 FEET ABOVE A TRUCK ON THE STREET; CONTACT NAME		phone	
			Completed	2		07/13 16 35		07/13 16 28	16 42	16 42	16 43	0.9	0.0	10	-10.0	0.9	5.6	-4.7	0686573094	0	AD		1160	0930				Access/Safety Dogs); AXS UNKNOWN, WIRE LOW RUNNING ACCROSS THE STREET STATES THAT IF A TRUCK PASSES BY THEY WILL TAKE TH WIRE WITH THEM WIRE CALLED IN TWO HOURS AGO FROM NEIGHBORHS ADDRESS AND NO ON HAS ARRIVED YET		phone	

Det 7/13/2021
 Chic

Tech Info			Dispatch Info					FO Timestamp Info				Elapsed Times						Order Info															
Area	HQ	Tech	Order State	Order Dispatch Count	Dispatch User ID	Last Dispatch Timestamp	Returned to Pending	Date Taken Timestamp	Enroute Time	Onsite Time	Completed Time	Total Time Billed To Order	En Route Minutes	Expected HQ Drive Time	Variance	On Site Minutes	Total Expected CC Time	Variance	Order Number	Priority	Appointment Window	Address	Job Code 1	CC1	CC2	CC3	CC4	Office Remarks	Dispatcher Remarks	Tech Remarks			
			Completed	1		07/13 15 20		07/13 15 20	16 44	18 23	18 24	100.5	99.6	10	89.6	0.9	5.6	-4.7	T005340973	1	AD										AXS-DOGS ON PREMISE XSTR-COHSSET PWR-I CUSTOMER IS OUT OF POWER, PREVIOUS TR REPORT ON FILE HOWEVER ISSUE NOT RESOLVED, CUSTOMER STILL HAS NO POWER, CUST STATED DAMAGED ELECTRICAL METER BOX WAS DAMAGED BY AN UMBRELLA.		meter problem
			Completed	1		07/13 15 50		07/13 15 50	18 49	19 15	19 16	26.7	26.0	10	16.0	0.7	5.6	-4.9	T005340908	1	AD										AXS-OK XSTR-NORD PWR-Y NO ELECTRIC SERVICE, WENT OUT APPROX. 10PM YESTERDAY, PWR ON PER SSCKD MAIN OUTSIDE, AND GFI IN BATHROOM		breaker
			Cancelled	2		07/13 06 22		07/08 14 56			06 53								X316144369	2	AD									(2) T-MAN TO INSTALL 140' NEW 40 TPX SVC & SET 200A 120/240 1P B10S MTR - FLD CNT			
			Reassigned	1		07/13 16 21		07/13 16 21			16 27								T005340928	1	AD									AXS-AXS OK XSTR-QUARTZ ST PWR-I WIRE DOWN ACCROSS THE ROAD IF A TRUCK DRIVE STHROUGH THEY RE TAKING THE LINE WITH THEM. CALL			